

	Inspection report	Sample Testing	RESULT PENDING
	Inspection number	INR-2208007	
	Inspection Date	15/08/2022	

Buyer	MOBI MOVEL	QC Approval	Colin
Supplier	ZHEJIANG JINPAN	QC Team	
Factory			

Order Details

PO NUMBER	MODEL	Brand	QTY
DG22-BL0031	E-SCOOTER	Mobimove	1

DIMENSION

Item	Unit	Spec	Sample1	Sample2	Sample3	Sample4	Sample5
------	------	------	---------	---------	---------	---------	---------

WEIGHT

Item	Unit	Spec	Value	Material
------	------	------	-------	----------

REMARKS /FINDINGS

1. Product Specifications			PASSED
1.1	Appearance	Black exterior	PASSED
1.2	Color of product		PASSED
1.3	Size and Weight		PASSED
1.4	Logo and Label		PASSED
2. Functionnal testing			PENDING
		2.4 ★ Walk mode level max 5 km:h : actual tested xxx km/h - Std speed level max15 km/h : actual tested is xxx km/h - Max speed 20 km/k, actual tested is xxx km/h	
		2.9 ★ Need to test after sample fixed	
2.1	Brake System	Brake system test OK	PASSED
2.2	Weight Limit	120 kg tested	PASSED
2.3	Loading Speed	120 kg for 1 mn	PASSED
2.4	Speed display	★ Walk mode level max 5 km:h : actual tested xxx km/h - Std speed level max15 km/h : actual tested is xxx km/h - Max speed 20 km/k, actual tested is xxx km/h	FAILED
2.5	Climbing	120 kg load, gentle slope at angel 20°	PASSED
2.6	Handlebat strength	50kg forward grip, hold hard 1mn OK	PASSED
2.7	Adaptor output	54,12v / 1,92 A	PASSED
2.8	Battery voltage		PASSED
2.9	Battery Charging time	★ Need to test after sample fixed	FAILED
2.10	Headlight and tailing function		PASSED
2.11	Bell test (electrical and mechanical)		PASSED
2.12	Pull Test		PASSED
2.13	Water proof test	Simulate IPX4 test for 10mn	PASSED
2.14	Fold Test		PASSED

	Inspection report	Sample Testing
	Inspection number	INR-2208007
	Inspection Date	

2.15

Suspension test

PASSED

3. Safety	3.1 Check in MP	PENDING
-----------	-----------------	---------

3.1

Short circuit test

Check in MP

PENDING

3.2

Internal Check

PASSED

4. Improvment		PENDING
---------------	--	---------

4.1

Improvments

Found back of wheel was very tightrn and make noise when moving

PENDING

5. Remarks	5.1 ★ Battery full charge need to check in MP 5.2 The wheel all screw has add glue to prevent screw not enoughtighten	PENDING
------------	--	---------

5.1

Remark 1

★ Battery full charge need to check in MP

PENDING

5.2

Remark 2

The wheel all screw has add glue to prevent screw not enoughtighten

PENDING

5.3

Remark 3

NA

	Inspection report	Sample Testing	RESULT
	Inspection number	INR-2208007	PENDING
	Inspection Date	15/08/2022	

Buyer	MOBI MOVEL	QC Approval	Colin
Supplier	ZHEJIANG JINPAN	QC Team	
Factory			

Order Details			
PO NUMBER	MODEL	Brand	QTY
DG22-BL0031	E-SCOOTER	Mobimove	1

1. PRODUCT SPECIFICATIONS	PASSED
---------------------------	--------

1.1 / Product Specifications - Appearance

PASSED

Black exterior



	Inspection report	Sample Testing
	Inspection number	INR-2208007
	Inspection Date	15/08/2022

1.2 / Product Specifications - Color of product

PASSED



	Inspection report	Sample Testing
	Inspection number	INR-2208007
	Inspection Date	15/08/2022



1.3 / Product Specifications - Size and Weight

PASSED



MMK ASIA LIMITED	Inspection report	Sample Testing
	Inspection number	INR-2208007
	Inspection Date	15/08/2022



	Inspection report	Sample Testing
	Inspection number	INR-2208007
	Inspection Date	15/08/2022




1.4 / Product Specifications - Logo and Label

PASSED



MMK ASIA LIMITED	Inspection report	Sample Testing
	Inspection number	INR-2208007
	Inspection Date	15/08/2022





15/08/2022 23:20:42



15/08/2022 23:20:47



15/08/2022 23:20:52



15/08/2022 23:20:56

2. FUNCTIONAL TESTING

PENDING

2.2 / Functionnal testing - Weight Limit

PASSED

120 kg tested



15/08/2022 23:23:42

	Inspection report	Sample Testing
	Inspection number	INR-2208007
	Inspection Date	15/08/2022

2.4 / Functionnal testing - Speed display

FAILED

★ Walk mode level max 5 km:h : actual tested xxx km/h - Std speed level max15 km/h : actual tested is xxx km/h - Max speed 20 km/k, actual tested is xxx km/h



15/08/2022 23:21:29



15/08/2022 23:21:34



15/08/2022 23:21:39




15/08/2022 23:21:43

2.6 / Functionnal testing - Handlebat strength

PASSED

50kg forward grip, hold hard 1mn OK



	Inspection report	Sample Testing
	Inspection number	INR-2208007
	Inspection Date	15/08/2022

2.8 / Functionnal testing - Battery voltage



PASSED



2.9 / Functionnal testing - Battery Charging time

FAILED



★ Need to test after sample fixed



	Inspection report	Sample Testing
	Inspection number	INR-2208007
	Inspection Date	15/08/2022


2.10 / Functionnal testing - Headlight and tailing function

PASSED



2.12 / Functionnal testing - Pull Test

PASSED




	Inspection report	Sample Testing
	Inspection number	INR-2208007
	Inspection Date	15/08/2022

2.13 / Functionnall testing - Water proof test

PASSED

Simulate IPX4 test for 10mn




3. SAFETY

PENDING

3.2 / Safety - Internal Check

PASSED





15/08/2022 23:24:52



15/08/2022 23:24:57



15/08/2022 23:25:01

5. REMARKS

PENDING

5.2 / Remarks - Remark 2

PENDING

The wheel all screw has add glue to prevent screw not enough tighten



15/08/2022 23:16:03



15/08/2022 23:16:23

The wheel all screw has add glue, to prevent the screw not enough tighten or screw from falling off , and glue to cover edge of screw. Inspection needs to check